

PAPST


Connection Diagram




Speed vs PWM



Tacho Output Signal "/22"





Tacho Output	2 pulses per revolution
$U_{s\ high}$	4,5 ... 6,0 V DC at I_{source} = 10 mA
$U_{s\ low}$	<= 0,7 V DC at I_{sink} = 1 mA
t_1 / t_2	0,8 - 1,2