**R4E280-AN67-11**

# AC centrifugal fan

backward curved

**ebm-papst Mulfingen GmbH & Co. KG**
Bachmühle 2 · D-74673 Mulfingen
Phone +49 7938 81-0
Fax +49 7938 81-110
info1@de.ebmpapst.com
www.ebmpapst.com

Limited partnership · Headquarters Mulfingen
County court Stuttgart · HRA 590344

General partner Elektrobau Mulfingen GmbH · Headquarters Mulfingen
County court Stuttgart · HRB 590142

## Nominal data

| | | |
|---|---|---|
| **Type** | **R4E280-AN67-11** | |
| **Motor** | **M4E068-DF** | |
| Phase | | 1~ |
| Nominal voltage | VAC | 230 |
| Frequency | Hz | 50 |
| Type of data definition | | cu |
| Valid for approval / standard | | CE |
| Speed (rpm) | $min^{-1}$ | 1090 |
| Power input | W | 88 |
| Current draw | A | 0.39 |
| Motor capacitor | µF | 3 |
| Capacitor voltage | VDB | 400 |
| Capacitor standard | | S2 (CE) |
| Min. back pressure | Pa | 0 |
| Min. ambient temperature | °C | -25 |
| Max. ambient temperature | °C | 45 |
| Starting current | A | 0.55 |

ml = Max. load · me = Max. efficiency · fa = Running at free air · cs = Customer specs · cu = Customer unit
Subject to alterations

# AC centrifugal fan

backward curved

## Technical features

| | |
|---|---|
| **Mass** | 2.3 kg |
| **Size** | 280 mm |
| **Surface of rotor** | Coated in black |
| **Material of impeller** | PA plastic |
| **Number of blades** | 9 |
| **Direction of rotation** | Counter-clockwise, seen on rotor |
| **Type of protection** | IP 44; Depending on installation and position as per EN 60034-5 |
| **Insulation class** | "B" |
| **Humidity (F)/environmental protection class (H)** | H0+ |
| **Max. permissible ambient motor temp. (transp./ storage)** | + 80 °C |
| **Min. permissible ambient motor temp. (transp./storage)** | - 40 °C |
| **Mounting position** | Shaft horizontal or rotor on bottom; rotor on top on request |
| **Condensate discharge holes** | Rotor-side |
| **Operation mode** | S1 |
| **Motor bearing** | Ball bearing |
| **Speed steps** | 3 |
| **Touch current acc. IEC 60990 (measuring network Fig. 4, TN system)** | < 0.75 mA |
| **Motor protection** | Thermal overload protector (TOP) wired internally |
| **Cable exit** | Variable |
| **Protection class** | I (if protective earth is connected by customer) |
| **Product conforming to standard** | EN 60335-1; CE |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 (0) 7938 81-0 · Fax +49 (0) 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# AC centrifugal fan

backward curved

## Product drawing




| | |
|---|---|
| 1 | Accessory part: Inlet nozzle 31050-2-4013 not included in scope of delivery |
| 2 | Thread reach max. 5 mm |
| 3 | Connection line PVC 7G 0.5 mm², 1x connector housing Phönix 6-pole 1757051 (MSTB 2.5/6-ST/5.08), 1x lead tip (green/yellow) crimped |
| 3.1 | Red (capacitor) |
| 3.2 | white (level 1) |
| 3.3 | grey (level 2) |
| 3.4 | black (level 3) |
| 3.5 | blue (N) |
| 3.6 | Orange (capacitor) |
| 4 | Grommet 64901-4-7011 EPDM black |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 (0) 7938 81-0 · Fax +49 (0) 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# AC centrifugal fan

backward curved

## Accessory part




Inlet nozzle 31050-2-4013 not included in scope of delivery




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 (0) 7938 81-0 · Fax +49 (0) 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# AC centrifugal fan

backward curved

## Connection screen




Note: Fast speed (step III); slow speed (step I)

| | | | | | |
|---|---|---|---|---|---|
| 1 | N (blue) | 2 | Capacitor (red) | 3 | Capacitor (orange) |
| 4 | Level 1 (white) | 5 | Level 2 (grey) | 6 | Level 3 (black) |
| 7 | L1 | 8 | PE (green/yellow) | | |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 (0) 7938 81-0 · Fax +49 (0) 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# AC centrifugal fan

backward curved

## Charts: Air flow 50 Hz




ρ = 1.15 kg/m³ ± 2 %

Measurement: LU-66162-1
Measurement: LU-66163-1
Measurement: LU-66164-1

Air performance measured as per ISO 5801 Installation category A. For detailed information on the measuring set-up, please contact ebm-papst. Suction-side noise levels: LwA measured as per ISO 13347 / LpA measured with 1m distance to fan axis. The values given are valid under the measuring conditions mentioned above and may vary according to the actual installation situation. With any deviation from the standard set-up, the specific values have to be checked and reviewed with the unit installed.

## Measured values

| | Stage | U | f | n | $P_e$ | I | $LpA_{in}$ | $q_V$ | $q_V$ | $p_{fs}$ |
|---|---|---|---|---|---|---|---|---|---|---|
| | | V | Hz | $min^{-1}$ | W | A | dB(A) | $m^3/h$ | cfm | inH2O |
| 1 | 3 | 230 | 50 | 1090 | 88 | 0.39 | 50 | 965 | 570 | 0.00 |
| 2 | 2 | 230 | 50 | 930 | 74 | 0.33 | 46 | 805 | 475 | 0.00 |
| 3 | 1 | 230 | 50 | 630 | 55 | 0.26 | 35 | 530 | 310 | 0.00 |

U = Supply voltage · f = Frequency · n = Speed (rpm) · $P_e$ = Power input · I = Current draw · $LpA_{in}$ = Sound pressure level inlet side · $q_V$ = Air flow



ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 (0) 7938 81-0 · Fax +49 (0) 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com