**R1G225-AG03-18**

# EC centrifugal fan

backward curved, single inlet



**ebm-papst Mulfingen GmbH & Co. KG**
Bachmühle 2 · D-74673 Mulfingen
Phone +49 7938 81-0
Fax +49 7938 81-110
info1@de.ebmpapst.com
www.ebmpapst.com

Limited partnership · Headquarters Mulfingen
County court Stuttgart · HRA 590344

General partner: Elektrobau Mulfingen GmbH · Headquarters Mulfingen
County court Stuttgart · HRB 590142

## Nominal data

| | | |
|---|---|---|
| **Type** | **R1G225-AG03-18** | |
| **Motor** | **M1G074-CF** | |
| Nominal voltage | VDC | 27 |
| Nominal voltage range | VDC | 18 .. 30 |
| Type of data definition | | fa |
| Speed | min-1 | 2850 |
| Power input | W | 122 |
| Current draw | A | 5 |
| Min. ambient temperature | °C | -25 |
| Max. ambient temperature | °C | +70 |

ml = max. load · me = max. efficiency · fa = running at free air · cs = customer specs · cu = customer unit
Subject to alterations

# EC centrifugal fan

backward curved, single inlet

## Technical features

| | |
|---|---|
| **Mass** | 1.8 kg |
| **Size** | 225 mm |
| **Surface of rotor** | Coated in black |
| **Material of impeller** | Plastic PA66, fibreglass-reinforced, round sheet-metal plate coated in black |
| **Number of blades** | 7 |
| **Stability** | Salt fog resistant in accordance with TELCORDIA GR-487-CORE, release No. 2, March 2000 |
| **Direction of rotation** | Clockwise, seen on rotor |
| **Type of protection** | IP 44 |
| **Insulation class** | "B" |
| **Humidity class** | F4-2 |
| **Max. permissible ambient motor temp. (transp./ storage)** | +80 °C |
| **Min. permissible ambient motor temp. (transp./storage)** | -40 °C |
| **Mounting position** | Any |
| **Condensate discharge holes** | None |
| **Operation mode** | S1 |
| **Motor bearing** | Ball bearing |
| **Technical features** | - Control input 0-10 VDC / PWM<br>- Tach output<br>- Motor current limit<br>- Soft start |
| **EMC interference immunity** | Acc. to EN 61000-6-2 |
| **EMC interference emission** | Acc. to EN 61000-6-3 |
| **Motor protection** | Reverse polarity and locked-rotor protection |
| **Cable exit** | Variable |
| **Product conforming to standard** | EN 60950-1 |
| **Approval** | CSA C22.2 Nr.77; UL 1004-1 |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 7938 81-0 · Fax +49 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# EC centrifugal fan

backward curved, single inlet

## Product drawing




| | |
|---|---|
| 1 | Connection line AWG20, 4 x brass lead tips crimped |
| 2 | Accessory part: Inlet nozzle 96358-2-4013, not included in the standard scope of delivery |
| 3 | Depth of screw max. 6 mm |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 7938 81-0 · Fax +49 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# EC centrifugal fan

backward curved, single inlet

## Connection screen




| Line | No. | Signal | Colour | Function / assignment |
|---|---|---|---|---|
| 1 | 1 | Un +27 V | red | Power supply 27 VDC, residual ripple 3.5 % |
| 1 | 2 | PWM / lin | yellow | PWM / lin, control input, 0-10 V |
| 1 | 3 | DUE | white | Speed monitoring output, 3 pulses per revolution, Isink max = 10 mA |
| 1 | 4 | GND | blue | Reference mass |




ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 7938 81-0 · Fax +49 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com

# EC centrifugal fan

backward curved, single inlet

## Charts: Air flow




Measurement: LU-122351
Measurement: LU-122349
Measurement: LU-122348
Measurement: LU-122352

Air performance measured as per ISO 5801 Installation category A. For detailed information on the measuring set-up, please contact ebm-papst. Suction-side noise levels: LwA measured as per ISO 13347 / LpA measured with 1m distance to fan axis. The values given are valid under the measuring conditions mentioned above and may vary according to the actual installation situation. With any deviation from the standard set-up, the specific values have to be checked and reviewed with the unit installed.

## Measured values

| | U | n | $P_e$ | I | qv | $p_{sf}$ |
|---|---|---|---|---|---|---|
| | V | $min^{-1}$ | W | A | $m^3/h$ | Pa |
| 1 | 30 | 2990 | 142 | 5.17 | 1190 | 0 |
| 2 | 30 | 2855 | 145 | 5.35 | 945 | 163 |
| 3 | 30 | 2815 | 146 | 5.40 | 760 | 267 |
| 4 | 30 | 2895 | 144 | 5.29 | 500 | 428 |
| 5 | 27 | 2815 | 120 | 4.84 | 1120 | 0 |
| 6 | 27 | 2730 | 126 | 5.10 | 910 | 150 |
| 7 | 27 | 2695 | 127 | 5.17 | 740 | 250 |
| 8 | 27 | 2750 | 125 | 5.04 | 485 | 400 |
| 9 | 24 | 2630 | 95 | 4.31 | 1040 | 0 |
| 10 | 24 | 2535 | 102 | 4.65 | 845 | 131 |
| 11 | 24 | 2510 | 104 | 4.74 | 685 | 216 |
| 12 | 24 | 2560 | 100 | 4.56 | 450 | 342 |
| 13 | 18 | 2165 | 54 | 3.35 | 855 | 0 |
| 14 | 18 | 2090 | 59 | 3.62 | 690 | 86 |
| 15 | 18 | 2075 | 60 | 3.68 | 555 | 143 |
| 16 | 18 | 2115 | 57 | 3.52 | 365 | 224 |



ebm-papst Mulfingen GmbH & Co. KG · Bachmühle 2 · D-74673 Mulfingen · Phone +49 7938 81-0 · Fax +49 7938 81-110 · info1@de.ebmpapst.com · www.ebmpapst.com